EXHIBIT 39

From:

Raymond DeGiorgio

To:

Brian Stouffer

CC:

Brian Thompson; David DeFrain

BCC:

Sent Date:

2012-10-05 14:10:27:000

Received Date:

2012-10-05 14:10:28:000

Subject:

Re: 2005-7 Cobalt and Ignition Switch Effort

Attachments:

Brain,

Due to the low volume (I am thinking we would only replaced switches on vehicles which the customer brought into the dealer), I would expect the price of the switch to cost approx. \$150.00.

If we replaced switches on ALL the model years i.e. 2005, 2006, 2007 the piece price would be about \$10.00 per switch. This cost is based on volume of 1.5 Million unites total.

Best Regards,

Raymond DeGiorgio Switch Lead Engineer

Brian Stouffer—10/05/2012 09:36:50 AM—Ray, Thanks for the estimate. Do you know the approximate price for the service part (i.e. what d

From:

Brian Stouffer/US/GM/GMC

To: Cc: Raymond DeGiorgio/US/GM/GMC

: Brian Thompson/US/GM/GMC

David DeFrain/US/GM/GMC

Date: 10/05/2012 09:36 AM

Subject: Re: 2005-7 Cobalt and Ignition Switch Effort

Ray,

Thanks for the estimate. Do you know the approximate price for the service part (i.e. what dealers pay for the switch)?

Brian Stouffer
Product Investigation
ph

Raymond DeGiorgio—10/05/2012 09:33:18 AM—Brian, Not knowing what my requirements are I will take a SWAG at the Torque required for a new swit

From:

Raymond DeGiorgio/US/GM/GMC

To: Cc: Brian Stouffer/US/GM/GMO

Date: 10/

Brian Thompson/US/GM/GMC 10/05/2012 09:33 AM David DeFrain/US/GM/GMO

09-50026-mg Doc 12640-39 Filed 04/23/14 Entered 04/23/14 18:52:12 Pq 3 of 4

Subject: Re: 2005-7 Cobalt and Ignition Switch Effort

Not knowing what my requirements are I will take a SWAG at the Torque required for a new switch. Here is my high level proposal:

Assumption is 100 N cm Torque.

- New switch design = Engineering Cost Estimate approx. \$300,000
- Lead Time = 18 24 months from issuance of GM Purchase Order and supplier selection.

Let me know if you have any additional questions.

Best Regards,

Raymond DeGiorgio Switch Lead Engineer

Brian Stouffer—10/05/2012 09:05:05 AM—Ray, As I said in my original statement, I currently don't know what the torque value needs to be.

From:

Brian Stouffer/US/GM/GMC

To: Cc:

Raymond DeGiorgio/US/GM/GMO

Brian Thompson/US/GM/GMC

David DeFrain/US/GM/GMC

10/05/2012 09:05 AM Date:

Re: 2005-7 Cobalt and Ignition Switch Effort Subject:

Ray,

As I said in my original statement, I currently don't know what the torque value needs to be. Significant work is required to determine the torque. What is requested is a high level understanding of what it would take to create a new switch.

Brian Stouffer Product Investigation

Raymond DeGiorgio -- 10/05/2012 07:39:19 AM -- Brian, In order to provide you with a HIGH level proposal, I need to understand what my requirements

David DeFrain/US/GM/GMO

From:

Raymond DeGiorgio/US/GM/GMC

To:

Brian Stouffer/US/GM/GMC

Cc: Date: Brian Thompson/US/GM/GMO

10/05/2012 07:39 AM

Subject:

Re: 2005-7 Cobalt and Ignition Switch Effort

Brian,

In order to provide you with a HIGH level proposal, I need to understand what my requirements are.

what is the TORQUE value that you desire?

Without this information I cannot develop a proposal.

Best Regards,

Raymond DeGiorgio Switch Lead Engineer

Brian Stouffer—10/04/2012 04:07:13 PM—Ray, At today's Jim Federico update on the 2005-7 Cobalt airbag investigation our primary discussion

From: Brian Stouffer/US/GM/GMC

To: Raymond DeGiorgio/US/GM/GMC

Cc: David DeFrain/US/GM/GMC Brian Thompson/US/GM/GMC

Date: 10/04/2012 04:07 PM

Subject: 2005-7 Cobalt and Ignition Switch Effort

Ray,

At today's Jim Federico update on the 2005-7 Cobalt airbag investigation our primary discussion was on what it would take to keep the SDM active if the ignition key was turned to the accessory mode. In addition to that, we also discussed other potential options. One mentioned was revising the ignition switch to increase the effort to turn the key from Run to Accessory. The torque value desired is TBD.

For our next Federico update (approximate 2 weeks), please develop a high level proposal on what it would take to create a new switch for service with higher efforts.

Thanks,

Brian Stouffer
Product Investigation